






AGM Battery Packing Instructions – EAA-AGM (Ground shipments)

1	Ensure that the battery terminals are secured to prevent the battery from short-circuiting. Electrical tape may be used to secure the ends of the terminals.	
2	Wrap the battery in the bubble wrap (provided) and slip the wrapped battery into the zip lock bag (provided). Zip lock the bag.	
3	Place the sealed bag with the battery AGM in the fiberboard box (provided). Fill any void space with additional packaging material to prevent movement. Part should be secure within the fiberboard box.	
4	Ensure the box includes orientation arrows. They must be pointing up in accordance with the battery & label placement.	
5	Confirm that the fiberboard box is labeled with the NONSPILLABLE BATTERY label. Be sure it is visible and not covering any other marks or labels.	
6	Place the Return Authorization Paperwork in the box. Parts cannot be credited without the requisite paperwork. Seal the box with the precut tape (provided).	


AGM Battery Packing Instructions – EAA-AGM (Ground shipments)

2/2

7 Generate shipper and shipping paperwork utilizing your UPS Hazardous Materials software on your computer.



8 Attach the packing slip envelope to the top of the completed package. Provide at least one (1) copy of the hazardous declaration and Emergency Response Guide 154 (provided) to the driver.



Questions? Please contact Tina Martin at +1 (586) 582-5833 or James Brozovich at +1 (586) 582-5835